

isit:

arwells. We (W&S and DPW staff) decided not to drain them down all the
y sediment in the clearwells. We were able to see the interior walls from a
1 about 3' water left in them (again – didn't want to stir up trouble).
vented a close inspection of the walls and the bottom, as did the staining on
oth clearwells looked to be in good condition and likely will not require
tion. A final assessment, however, will need to be made once the clearwells

orescence on the exterior wall of the building. Our structural engineer
be repaired by drilling along the affected area and injecting a sealer. This
rior.

ardown test to compare the results of the plant effluent meter - summary is in
ulation, there seems to be a slight discrepancy between the calculated
meter slightly over-registering (2.5% and 5%).

flow meter:

ft²

l ft = 462.53 ft³ = 3,460 gal/ft/tank = 6,920 gal/ft (for two tanks)

Calculated Flow	Flow Meter
227 gpm	239 gpm
230.7 gpm	237 gpm

make sense to have the meter calibrated.

values that OCDOH wants – VRI has not provided the requested information,
ome charts of the clearwell level. They indicate the clearwell routinely drops
umbers for our reply to OCDOH, though they're lower than we hoped. We
against actual depth and it checked out – i.e. the clearwell levels indicated on
curate.

nmend:

ll at a time.

ment; use blowdown valve to dump the tank during this procedure

ly and dump clearwell