

**VILLAGE OF TUXEDO PARK**  
P.O. BOX 31  
80 LORILLARD ROAD  
TUXEDO PARK, NEW YORK 10987

**DPW Report**  
**August 16, 2021 to September 13, 2021**

**Roads**

1. Scraped and painted iron gates at entrance to the Village
2. Installed cobblestone planters in front and behind new Police Booth
3. Replaced the glass in the lights at the main gate and painted
4. Removed large yew from in front of the Lodge and replanted on the side of the Keep
5. Lifted dam board at Tuxedo Lake and opened valve at Pond 3 dam during heavy rains
6. Cleaned up fallen trees on Pine Road, Ridge Road, East Lake Road, and Camp Comfort Road
7. Cleaned drains and catch basins before and after heavy rains
8. Removed brush and debris from behind stone wall on Summit Road
9. Cut back brush on Summit Road, West Lake Road and Turtle Point Road ahead of paving in October
10. Planted shrubs in the new beds at the Police Booth
11. Cut grass throughout the month
12. Cleaned gutters at the Village Office
13. Cut grass throughout the month
14. Spread mulch by the Police Station
15. Formed and poured a concrete foundation for the A/C unit at the Booth
16. Poured concrete walkway at the entrance to the Booth
17. Patched potholes on Summit Road
18. Removed old railroad ties around triangle on West Lake Road by Brook Road and began installing a stone border
19. Removed one of two one-way signs at the bottom of Continental Road
20. Weed-wacked Pepperidge Road

**Water**

1. Repaired non-working water meters
2. Checked Turtle Point Road pump station regularly
3. Filled chemical crocks at the Water Plant
4. Prepared and sent monthly water report to the Health Department
5. Located and marked water valve boxes and manholes on roads to be ground up and paved
6. Repaired two small leaks on a 1" copper line at the Water Plant
7. Greased pumps and motors at the Water Plant
8. Did monthly water samples
9. Cleaned leaves and debris from around the Regulator Building in the Hamlet
10. Took weekly readings of Village-owned accounts
11. Changed oil and filters on the air compressor at the Water Plant
12. Greased pumps and motors at the Mountain Farm pump station

13. Checked water and sewer lines at the Yannuzi residence after receiving a call of a wet spot on the property. No noise found on water lines and no blockages in sewer line.

### **Sewer**

1. Had sludge removed from the sewer plant
2. Performed daily maintenance at the Sewer Plant
3. Did bi-monthly sampling at Sewer Plant
4. Prepared and sent monthly sewer report to the DEC
5. Installed a new water spigot in the chlorine room at the Sewer Plant