

BUILDING DEPARTMENT - APPLICATION/PERMIT
VILLAGE OF TUXEDO PARK-LORILARD ROAD-TUXEDO PARK, N.Y. 10987 845-351-4745

PROPERTY LOCATION - SECTION 106 BLOCK 1 LOT 7

OWNER: Schmidtburg PROPERTY STREET ADDRESS East Lake R.P. 36

MAILING ADDRESS 36 East Lake R.D. Tuxedo Park TELEPHONE 914 351 1226

NATURE OF CONSTRUCTION NEW ALTERATION ADDITION RECONSTRUCTION

ACCESSARY USE OTHER-DESCRIBE Town House Unit

IF STRUCTURE BRIEF DESCRIPTION

ESTIMATED COST OF CONSTRUCTION \$ 30,000

THE OWNER/AGENT William F. Pinclogh CERTIFIES THAT HE IS THE OWNER OR AGENT OF ALL THAT CERTAIN LOT, PIECE OR PARCEL OF LAND AND OR BUILDING DESCRIBED IN THE APPLICATION AND IF NOT THE OWNER THAT HE HAS BEEN DULY AND PROPERLY AUTHORIZED TO MAKE THIS APPLICATION AND TO ASSUME RESPONSIBILITY FOR THE OWNER IN CONNECTION WITH THIS APPLICATION AND AGREES THAT THE VILLAGE OF TUXEDO PARK ZONING ORDINANCE AND STATE OF NEW YORK BUILDING CODES WILL BE COMPLIED WITH AS WELL AS ANY OTHER REGULATIONS RELATING TO THE CONSTRUCTION OR USE OF THE PROPOSED BUILDING AND LAND HERE

Registration No. 01LE5053631

NOTARY Qualified in Orange County

Commission Expires DECEMBER 26, 2008

**** SIGNED

William F. Pinclogh LICENSED ENGINEER NAME

ADDRESS

TELEPHONE

BUILDING OR CONTRACTOR Bantlat Tank Service

ADDRESS

TELEPHONE 914-879-9754

BUILDERS INSURANCE INFORMATION: WORKMENS COMPENSATION #

LIABILITY #

AGENT OR COMPANY

ADDRESS

TELEPHONE

VILLAGE CLERK: DATE RECEIVED 2/17/08 FEE PAID CLC #55853 \$200

BUILDING INSPECTOR: PRELIMINARY INSPECTION- APPROVED DISAPPROVED

DATE COMMENTS

BOARD OF ARCHITECTURAL REVIEW: APPROVED DISAPPROVED - DATE

SIGNATURES

AHRB. COMMENTS

BOARD OF TRUSTEES: APPROVED DISAPPROVED -- DATE

SIGNATURES

TRUSTEES COMMENTS:

I HAVE EXAMINED THIS APPLICATION AND THE PLANS (BUILDING AND PLOT) THAT ARE A PART OF THIS APPLICATION AND FIND THAT THEY ARE IN COMPLIANCE WITH THE VILLAGE OF TUXEDO PARK ZONING ORDINANCE AND HEREBY ISSUE THIS BUILDING PERMIT.

PERMIT # DATE OF ISSUE EXPIRATION DATE

SIGNED-BUILDING INSPECTOR/CODE ENFORCEMENT OFFICER



Client: 2340951

Mr Mike Schmitburger
36 East Lake Road
Tuxedo Park, NY 10987

Printed on: 8/18/2026

Created on: 8/18/2026

Bartlett Tree Experts
Mike McGowan - Representative
2240 Saw Mill River Road
Elmsford, NY 10523
Business: 914-592-4520
Fax Number: 914-592-5068
Mobile Phone: 914-879-9754
Bus. Reg. ID: 00529

NY Applicator Certification No.: C3851678 / C3809904

The following program is recommended for certain trees and shrubs on your property. In addition to a thorough plant health care program, or the specific services recommended, Bartlett Tree Experts also recommends having a tree risk assessment qualified arborist conduct a tree risk assessment on your property periodically to assist you in identifying potential risks of tree or limb failure and the potential consequences of such tree or limb failure relating to your trees and shrubs. An inspection of trees or shrubs for the purpose of writing a recommendation or conducting plant health care or tree care services is not a tree risk assessment. THIS IS NOT AN INVOICE.

Tree and Shrub Work:

Removal

Cut down the following tagged property items:

- Oak 384 located at the front of property near road
- Maple 481 located at the front of property
- Maple 485 located at the front of property
- Tulip 390 located at the front of property near road
- Spruce 510 located at the front of property
- Beech 9 located at the left side of property on driveway
- Hemlock 37 located at the left rear of property
- Oak 48 located at the left rear of property
- Hemlock 103 located at the left rear of property
- Poplar 156 located at the back of property
- Hemlock 230 located at the right side of property
- Maple 244 located at the right side of property
- Maple 258 located at the right side of property
- Maple 277 located at the right front of property
- Hemlocks 279-282 located at the right front of property
- Maple 296 located at the right front corner of property
- Maple 307 located at the right front of property
- Hornbeam 386 located at the front of property
- Ash 400 located at the left front of property

Client: 2340951

Printed on: 8/18/2026

Created on: 8/18/2026

- Sassafras 427 located at the left front of property

Leave stumps as close to grade as possible. Remove resulting debris.

Arborist Notes:

- Does not include stump grinding. To be discussed with client when trees are removed.

Includes all disposal fees

Tree and Shrub Work: Phase 1

Natural Pruning

Species	Location
Tagged trees	entire property

Goals:

- Reduce risk of branch failure

Specifications:

- Remove dead, declining, broken branches as needed, 2-12 inch diameter cut(s), entire canopy
- Remove all debris

Arborist Notes:

- Tree species and inventory #s:

Spruce 1, Maple 3, Tulip 20, Beech 22, Spruce 27, Spruce 28, Hemlock 29, Maple 31, Oak 39 (install support cable), Hemlock 54, Hemlock 57, Hemlock 80, Pine 81, Oak 157, Oak 163, Oak 164, Oak 165, Oak 166, Oak 167, Oak 168, Oak 169, Oak 170, Pine 198, Oak 199, Maple 250 (install support cable), Oak 263, Hemlock 265, Tulip 266, Tulip 273, Hickory 299, Tulip 303, Hickory 304, Oak 308, Oak 309, Oak 350, Oak 351 (install support cable), Maple 352, Oak 311 (install support cable), Oak 329 (install support cable), Oak 331 (cable), Tulip 341, Tulip 355, Tulip 358, Tulip 389, Tulip 393, Oak 396, Oak 397, Oak 398, Tulip 393 (cable), Tulip 423, Spruce 431, Tulip 439, Maple 440, Cedar 446, Cedar 447, Tulip 463, Tulip 464, Tulip 465, Tulip 471, Maple 480, Tulip 384, Spruce 508, Spruce 509, Maple 511, Spruce 513, Spruce 514, Spruce 515, Spruce 516

Client: 2340951

Printed on: 8/18/2026


Created on: 8/18/2026

Notice to Consumer

You, the buyer, may cancel this transaction at any time prior to midnight of the third business day after the date of this agreement. See the attached notice of cancellation form for an explanation of this right.

Please review the terms and conditions attached, which become part of the agreement, and sign and return one copy authorizing the program.

(Customer Signature)



(Bartlett Representative - Mike McGowan)

(Date)

8/18/2026

(Date)

* Sales tax added where applicable. Prices are guaranteed if accepted within thirty days.

All accounts are net payable upon receipt of invoice.

Work is done in accordance with ANSI A300 Tree Care Standards.

To access a certificate of liability insurance for Bartlett Tree Experts, please navigate to <http://www.bartlett.com/BartlettCOL.pdf>

A Job Site Safety Analysis was completed for your property, please contact your arborist for further details.

Bartlett Tree Experts does not sell client information to third parties. However, Bartlett may need to retain client information for digital advertising purposes. For further information on the type of client information collected, the purpose for which information may be used, and any client's ability to access and/or opt out of such use, please visit Bartlett's privacy policy on our website: <https://www.bartlett.com/privacy-policy.cfm>